



REPLACEMENT FOR

### AVENSIS '98-'02 CALDINA CT220



REPLACEMENT FOR

### AVENSIS '01-'02



REPLACEMENT FOR

### AVENSIS '03-'05

#### 212-1187-**RD**-**LD**-EM

HEAD LAMP LD;  
RD: R 81130-05140  
L 81150-05120 L 81170-05140  
6PCS 5.23CFT



H7/H7

#### 212-11C3-**RD**-**LD**-EM

HEAD LAMP LD;  
RD: R 81130-05080  
L 81170-05080 4PCS 4.69CFT  
LD: R 81130-05100  
L 81170-05100



H7/H7/W5W

#### 212-11F3-**RD**-**LD**-EM

HEAD LAMP LD;  
RD: R 81130-05160  
L 81170-05160 4PCS 7.61CFT



H7/H1/PY21W/W5W

W/S MOTOR

#### 212-15C7-**UE**

CORNER LAMP  
R 81510-05020  
L 81520-05020  
20PCS 2.77CFT



PY21W

#### 212-15G4-**AE**

CORNER LAMP  
R 81510-05030  
L 81520-05030  
20PCS 3.63CFT



P21W

#### 212-2036-**UE**

FOG LAMP  
R 81210-05060  
L 81220-05060  
12PCS 2.47CFT



H4

#### 212-19B5

TAIL LAMP  
R 81550-05050  
L 81560-05050  
10PCS  
CFT



TBA

#### 212-19L6

TAIL LAMP  
R 81551-05090  
L 81561-05090  
PCS CFT



TBA

#### 212-19G9 **R-LD-UE** **L-LD-UE**

TAIL LAMP  
R 81551-05140  
L 81561-05130  
PCS CFT



TBA

#### 212-19G9 **R-RD-UE** **L-RD-UE**

TAIL LAMP  
R 81551-05130  
L 81561-05140  
PCS CFT



TBA



TOYOTA



REPLACEMENT FOR  
**AVENSIS '06**

**212-11L1-RD-EM**  
HEAD LAMP LD  
LD:  
R 81130-05240 RD:  
L 81170-05240 L 81130-05220  
PCS L 81170-05220  
CFT

H7/H1/WY21W/W5W **TBA**

**212-11L1-LDH-M**  
HEAD LAMP  
R  
L 81130-05250  
PCS  
CFT


**TBA**

**212-2052-AQ/UQ**  
FOG LAMP  
R 81210-0D040  
L 81220-0D040  
12PCS  
1.80CFT

H11

**212-2060-UE**  
FOG LAMP  
R  
L PCS CFT

H11 **TBA**



**212-19P1 R-LD-UE** H/B  
TAIL LAMP L-LD-UE  
R 81561-05240  
L 81551-05240  
PCS CFT

**TBA**

**212-19N9 R-LD-UE** SEDEN  
TAIL LAMP L-LD-UE  
R 81551-05190  
L 81561-05210  
PCS CFT

**TBA**

**212-19N9 R-RD-UE** SOUTH AFRICA  
TAIL LAMP L-LD-UE SEDEN  
R 81551-05200  
L 81561-05220  
PCS CFT

**TBA**

**212-19P2 R-LD-UE** WAGON  
TAIL LAMP L-LD-UE  
R 81551-05220  
L 81561-05260  
PCS CFT

**TBA**